



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 15, 2013

Reviewed:

Mine Name: Goldstrike Mine	Permit Number: M/053/0005
Operator Name:	Inspection Date: 05/08/2013
Inspector(s): Lynn Kunzler	Time: 12:01 pm
Other Participants: None	Mine Status: reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Check status of wildlife guzzler installation

Inspection Summary:

During the fall of 2012, the Division had contracted with Wildlife Resources for the installation of a wildlife guzzler to improve wildlife habitat (the post mining land use for this project). Construction of the guzzler began lat November of 2012 and was 90% complete when the site was visited in December. At the time of this inspection, the Division had not been notified that the installation had been completed, nor had the Division received a billing statement for the project.

Upon arrival, it was noted that the guzzler site had been fenced. Closer examination revealed that the construction had been completed. The guzzler consists of a large collection apron, with the water being diverted into 3 partially buried tanks, with wildlife access. The tanks did have some water in them, but were not full. The entire area was fenced with a rail fence to keep grazing livestock away from the guzzler. After contacting DWR in Cedar City, they indicated that the fencing was completed last week and they were preparing the billing statement to submit.

Photos were taken of the completed project.

Conclusions and Recommendations:

The guzzler installation has been competed as per the MOU between DOGM and DWR. Once we receive the billing statement, we need to verify the amount (as per the MOU) and if correct, remit payment.

Inspector's Signature

O:\M053-Washington\M0530005-Goldstrike\inspections\Insp-05082013.doc